

3233 A/C COUPLING LEAK REPAIR CLAMP


FOR CLASS 150 PIPE

CASTINGS: Ductile Iron per ASTM A536.

GASKET: NBR produced from 100% new rubber to ensure performance under varying pressures with superior storage characteristics. Suitable for oil, mild acids, water, salt media and most aliphatic hydrocarbon fluids with a temperature range of -25°F to +248°F.

BOLTS & NUTS: Low alloy Steel per ASTM A325 and ASTM A563.

FINISH: Epoxy.



3233								
Nominal Pipe Size		Pipe OD Range		Approx Weight		Part Number	List Price	
Inches	MM	Inches	MM	lbs.	kgs.		A/C Coupling	Additional Gasket
4	100	5.07-5.20	129-132	25	11	3233040000HA	\$293.30	\$42.80
6	150	7.17-7.35	182-187	32	15	3233060000HA	\$337.00	\$53.20
8	200	9.37-9.50	238-241	37	17	3233080000HA	\$437.80	\$66.40

Gaskets	Part Number	List Price
4	V3233041	\$42.80
6	V3233061	\$53.20
8	V3233081	\$66.40

NOTE: This repair clamp is furnished with one gasket. If both ends of the A/C Coupling are leaking order one additional gasket.

HOW TO ORDER: Specify Model Number, and Pipe Size.

EXAMPLE: 8" 3233 A/C Coupling Leak Repair Clamp . Order 3233-8. **Part Number:** 3233080000HA .